



Photo: # 1 Site: D&Z Exploration, Inc. - Hastert East Lease, Garnett, KS Date: 8/26/2015
 Time: AM Direction: North Photographer: Paul Doherty, EPA Witness: Deke Belden, D&Z Exploration
 Description: Hastert East Lease tank battery. The plan states that the dike height is 1.5 feet which is not obvious from field observations.



Photo: # 2 Site: D&Z Exploration, Inc. - Hastert East Lease, Garnett, KS Date: 8/26/2015
 Time: AM Direction: North Photographer: Paul Doherty, EPA Witness: Deke Belden, D&Z Exploration
 Description: Hastert East Lease dikes have been reconstructed and oil inside and outside containment has been removed by ongoing remediation actions. Gypsum has been applied to soil outside containment at the direction of the KCC.



Photo: # 3 Site: D&Z Exploration, Inc. - Hastert East Lease, Garnett, KS Date: 8/26/2015
 Time: AM Direction: Southeast Photographer: Paul Doherty, EPA Witness: Deke Belden, D&Z Exploration
 Description: Northeast corner of containment has been reconstructed and oil contaminated soil has been excavated and the ground treated with gypsum under KCC over sight.



Photo: # 4 Site: D&Z Exploration, Inc. - Hastert East Lease, Garnett, KS Date: 8/26/2015
 Time: AM Direction: Northeast Photographer: Paul Doherty, EPA Witness: Deke Belden, D&Z Exploration
 Description: View Hastert East Lease tank battery inside containment.



Photo: # 5 Site: D&Z Exploration, Inc. - Hastert East Lease, Garnett, KS Date: 8/26/2015
 Time: AM Direction: North Photographer: Paul Doherty, EPA Witness: Deke Belden, D&Z Exploration
 Description: Example of wellhead in proximity to surface water (in background).



Photo: # 6 Site: D&Z Exploration, Inc. - Hastert East Lease, Garnett, KS Date: 8/26/2015
 Time: AM Direction: Northwest Photographer: Paul Doherty, EPA Witness: Deke Belden, D&Z Exploration
 Description: Another view of wellhead in proximity to surface water (in background). Peat moss absorbent applied to oil leakage at well head pump rods was indication that there is an active gathering line maintenance program in place.



Photo: # 7 Site: D&Z Exploration, Inc. - Hastert East Lease, Garnett, KS Date: 8/26/2015
 Time: AM Direction: Northwest Photographer: Paul Doherty, EPA Witness: Deke Belden, D&Z Exploration
 Description: Evidence of a well head rod bushing/gasket leak that had not yet been attended to. The situation was pointed out to the operator who agreed to address the situation.



Photo: # 8 Site: D&Z Exploration, Inc. - Hastert East Lease, Garnett, KS Date: 8/26/2015
 Time: AM Direction: Northwest Photographer: Paul Doherty, EPA Witness: Deke Belden, D&Z Exploration
 Description: View of peat moss absorbent applied to old well head oil release. Visual evidence was that the release had occurred under the previous lease operator and had run some distance away from the well head.



Photo: # 9 Site: D&Z Exploration, Inc. - Hastert East Lease, Garnett, KS Date: 8/26/2015
Time: AM Direction: Northwest Photographer: Paul Doherty, EPA Witness: Deke Belden, D&Z Exploration
Description: Another well head where peat moss absorbent has been applied to old well head oil release. Visual evidence was that the release had occurred under the previous lease operator and had run some distance away from the well head.